




Situatietekening

Belgetenseweg 8
5756 PP Vlieroten



Unit 1: 14,4 x 3,6 mtr.
 Unit 2: 6 x 6 mtr.
 Unit 3: 6 x 9 mtr.
 Unit 4: 6 x 3 mtr.

X Rookmelder
 O Co2 melder




Belgierseweg 8, 5756 PP Vlieland

Doorsneden

- unit 1: 14,4 x 3,6 mtr.
- unit 2: 6 x 6 mtr.
- unit 3: 6 x 9 mtr.
- unit 4: 6 x 3 mtr.

X Rookmelder
O Co2 melder



Belgiëseweg 8, 5756 PP Vlierden

VOORGEVEL

DUBBELE RAMEN


B. 1.80
H. 1.18

RAMEN
B. 0.90
H. 1.05

RAMEN
Achterste
ruit
B 97/2
H 1.13

14.6

12




Rechtergevel

RAAM
B 0.90
H 1.05

RAAM
B 0.90
H 0.95

RAAM
B 0.7 1/2
H 1.13



Linkergevel

Achterste
ruimte

Ramen

B. 97 1/2

H 1.13

Deur (blijft
gesloten)

B 0.90

H 2.10

Deur

B. 0.90


H 2.10

voorste
ruimte

Raam

B. 0.87


H 1.18



ACHTERGEVEL


RAMEN
B 97 1/2
H 1.13

WC RAAM
B 0.66
H 0.36



14,60 m'


Doorsnede A





2,60 m'

Doorsnede B

12,00 m'






unit 1: 14,4 x 36 mtr.
 unit 2: 6 x 6 mtr.
 unit 3: 6 x 9 mtr.
 unit 4: 6 x 3 mtr.

X Rookmelder
 O Co2 melder

WADI 8-10 m³
 infiltratie



② ③

Beleggenweg 8, 5756 PP Vlierden